
COARSE_50K_lin
FINE_50K_lin
Basic VCO
FM_50K_lin
0.1
PW_50K_lin
10n
100p
VCO/LFO
V/OCT
FM
SYNC
PWM
SINE
TRI
SAW
PULSE